



Certificate Number	17-KL3354765-A
Effective Date	13-JUL-2017
Expiry Date	12-JUL-2020
ABS Port Office	KUALA LUMPUR
Specialist's Website	www.teletime.com.my

CERTIFICATE OF Recognized External Specialist

This is to certify that

Tele Time Technology Sdn Bhd

located at

2A Jalan Ramin 3, Botanic Business Gateway, Bandar Botanic, Klang, Malaysia

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

Radio Communication Equipment Inspections and Testing

It is the responsibility of the Service Provider to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's website (noted above). The products and models allowed to be serviced are to be listed on the company's website. The ABS office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors, etc.




Thomas Yoon, Surveyor



Certificate Number	17-KL3354765-C
Effective Date	13-JUL-2017
Expiry Date	12-JUL-2020
ABS Port Office	KUALA LUMPUR
Specialist's Website	www.teletime.com.my

CERTIFICATE OF
Recognized External Specialist

This is to certify that

Tele Time Technology Sdn Bhd

located at

2A Jalan Ramin 3, Botanic Business Gateway, Bandar Botanic, Klang, Malaysia

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

Automatic Identification Systems Inspection, Performance Testing and Maintenance

It is the responsibility of the Service Provider to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's website (noted above). The products and models allowed to be serviced are to be listed on the company's website. The ABS office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors, etc.

Thomas Yoon, Surveyor



Certificate Number 17-KL3354765-B
Effective Date 13-JUL-2017
Expiry Date 12-JUL-2020
ABS Port Office KUALA LUMPUR
Specialist's Website www.teletime.com.my

CERTIFICATE OF Recognized External Specialist

This is to certify that

Tele Time Technology Sdn Bhd

located at

2A Jalan Ramin 3, Botanic Business Gateway, Bandar Botanic, Klang, Malaysia

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

Shore-based Maintenance of EPIRBs

It is the responsibility of the Service Provider to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's website (noted above). The products and models allowed to be serviced are to be listed on the company's website. The ABS office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors, etc.




Thomas Yoon, Surveyor